

**Plasma Cutting Systems**



**Powermax30**

Loss Value \$1,395.00

Standard Rental Rates:

\$ 85.00 per Day  
 \$170.00 per Week  
 \$340.00 per Month

Maximum Cutting Capacity	Air Requirements	Rated Output	Amps Input at Rated Output, 60 Hz, 1 - Phase		Weight
			115 V	230 V	
3/8" Mild Steel	3.5 SCFM at 65 PSI	30 A at 35% duty cycle	26	13.5	20 lb



**Powermax45**

Loss Value \$2,095.00

Standard Rental Rates:

\$ 90.00 per Day  
 \$180.00 per Week  
 \$360.00 per Month

Maximum Cutting Capacity	Air Requirements	Rated Output	Amps Input at Rated Output, 60 Hz, 1 - Phase		Weight
			230 V		
3/4" Mild Steel	6 SCFM	45 A at 132 VDC, 50% duty cycle	28		37 lb



**Powermax1000**

Loss Value \$2,870.00

Standard Rental Rates:

\$110.00 per Day  
 \$220.00 per Week  
 \$440.00 per Month

Maximum Cutting Capacity	Air Requirements	Rated Output	Amps Input at Rated Output, 60 Hz				Weight
			208 V	230 V	480 V	600 V	
1" Mild Steel	6.7 SCFM at 90 PSI	60 A at 140 VDC, 50% duty cycle, 3 - Phase	29	26	12	11	83 lb
		60 A at 140 VDC, 50% duty cycle, 1 - Phase	48	44	22		

Prices effective 4/21/2010; subject to change without notice.

**Plasma Cutting Systems**



**Powermax1250**

**Loss Value \$3,770.00**

**Standard Rental Rates:**

**\$125.00** per Day  
**\$250.00** per Week  
**\$500.00** per Month

Maximum Cutting Capacity	Air Requirements	Rated Output	Amps Input at Rated Output, 60 Hz				Weight
			208 V	230 V	480 V	600 V	
1 1/8" Mild Steel	6.7 SCFM at 90 PSI	80 A at 150 VDC, 60% duty cycle, 3 - Phase	40	37	17	17	97 lb
		80 A at 150 VDC, 50% duty cycle, 1 - Phase	70	60	31		



**Powermax1650**

**Loss Value \$5,030.00**

**Standard Rental Rates:**

**\$140.00** per Day  
**\$280.00** per Week  
**\$560.00** per Month

Maximum Cutting Capacity	Air Requirements	Rated Output	Amps Input at Rated Output, 60 Hz				Weight
			208 V	230 V	460 V	600 V	
1 1/2" Mild Steel	9.2 SCFM at 90 PSI	100 A at 160 VDC, 70% duty cycle, 3 - Phase	51	46	27	21	135 lb

Prices effective 4/21/2010; subject to change without notice.